

G = *Scusato*
F = *Filletatura*

G = *Subronced*
F = *Thread*


G = *Sanque*
F = *Filletaje*

G = *Subroncedo*
F = *Filote*

G = *Scusato*
F = *Sargy*

G = *Scusato*
F = *Fillet*

Queste serrature ed altre
Slide brackets, mortises and rollers lock




R 723.850 C=220 H=46
R 723.851 C=220 H=59
R 723.852 C=350 H=65
R 723.853 C=350 H=82



R 723.856 C=220 H=60
R 723.857 C=300 H=82




R 723.860 C=145 H=33



R 723.861 C=180 H=62



R 723.862 C=50 H=100



R 723.863 L=61 H=48

Nylon: R723.880 - R723.883 Ottone: R723.884 - R723.887

Nylon: R723.880 - R723.883 Brass: R723.884 - R723.887

Nylon: R723.880 - R723.883 Latton: R723.884 - R723.887

Nylon: R723.880 - R723.883 Latton: R723.884 - R723.887

Nylon: R723.880 - R723.883 Ottone: R723.884

Nylon: R723.880 - R723.883 Messing: R723.884 - R723.887

Ruota superiore
di guida in
ottone

Ruota superiore
di guida in
nylon

Ruota
superiore di
guida in latton

Ruota
superiore di
guida in nylon



R 723.870 D=30 H=26 F=M8
R 723.871 D=37 H=30 F=M10



R 723.873 D=34 H=30 F=M10
R 723.874 D=38 H=30 F=M10
R 723.875 D=34 H=30 F=M10



R 723.877 D=60 H=60

Terzo rondella e
di chiavi

Subronced lungo
molto ad illice

Forchelle, rondelle et
dis sont compris

Terzo rondella y
de las guarniciones

Charniere poliblock i
molto in polycarbon


Translucen sabre
plastic conico



R 723.880 D=25 H=32 F=M14
R 723.881 D=40 H=44 F=M16
R 723.882 D=30 H=40 F=M14
R 723.883 D=40 H=60 F=M16
R 723.884 D=25 H=32 F=M14
R 723.885 D=40 H=44 F=M16
R 723.886 D=30 H=40 F=M14
R 723.887 D=40 H=60 F=M16




R 723.897 D=192 B=50
R 723.898 D=115 B=70



R 723.900 L=90 H=98
R 723.901 L=110 H=104




R 723.902 L=110
H=262,5




R 723.904 C=42 A=59
R 723.905 C=52 A=69
R 723.906 C=62 A=79



R 723.910 C=25 A=35
R 723.911 C=25 A=42
R 723.912 C=25 A=52




R 723.950 B=210 L=25



R 723.951 B=118 L=21,5



R 723.957 C=42 H=216
R 723.958 C=52 H=216
R 723.959 C=62 H=216



R 723.965 C=42 H=216
R 723.966 C=52 H=216
R 723.967 C=62 H=216



R 723.914 C=25 A=35
R 723.915 C=25 A=42
R 723.916 C=25 A=52



R 723.970 C=25/35
R 723.971 C=35/45
R 723.972 C=40/50
R 723.973 C=50/60
R 723.974 C=25/35
R 723.975 C=35/45
R 723.976 C=40/50
R 723.977 C=50/60