

H 110 x L 110 mm

P 300 ■ 26 sp. 10 mm
P 301 ■ 31 sp. 10 mm




H 90 x L 90 mm

P 302 ■ 21 sp. 8 mm
P 303 ■ 26 sp. 8 mm



H 70 x L 70 mm

P 304 ■ 16,5 sp. 8 mm
P 305 ■ 21 sp. 8 mm



H 50 x L 50 mm

P 306 ■ 12,5 sp. 6 mm
P 307 ■ 16,5 sp. 6 mm



H 100 x L 100 mm

P 308 sp. 10 mm



H 110 x L 110 mm

P 300.01 sp. 10 mm




H 90 x L 90 mm

P 302.01 sp. 8 mm



H 70 x L 70 mm

P 304.01 sp. 8 mm



H 50 x L 50 mm

P 306.01 sp. 6 mm




H 100 x L 100 mm

P 309 sp. 10 mm



H 70 x L 70 mm

P 310 ■ 24 sp. 4 mm



H 100 x L 100 mm

P 311 sp. 10 mm



H 100 x L 100 mm

P 312 ■ 25 sp. 10 mm
P 313 ■ 30 sp. 10 mm



H 22 x L 120 mm

P 313.01




H 22 x L 120 mm

P 313.02 ● 50,5
P 313.03 ● 65,5
P 313.04 ● 80,5



H 20 x L 80 x 80 mm

P 314




H 20 x L 60 x 60 mm

P 315



H 20 x L 50 x 50 mm

P 316




H 20 x L 40 x 40 mm

P 317




H 20 x L 30 x 35 mm

P 318




H 20 x L 80 x 80 mm

P 319 ■ 30,5
P 320 ■ 35,5
P 321 ■ 40,5




H 20 x L 60 x 60 mm

P 322 ■ 25,5
P 323 ■ 30,5



H 20 x L 50 x 50 mm

P 324 ■ 16,5
P 325 ■ 18,5
P 326 ■ 20,5



H 20 x L 40 x 40 mm

P 327 ■ 12,5
P 328 ■ 14,5
P 329 ■ 16,5



H 20 x L 30 x 35 mm

P 330 ■ 12,5
P 331 ■ 14,5
P 332 ■ 12x15

Zincate

Zincate

P 319 Z ■ 30,5
P 320 Z ■ 35,5
P 321 Z ■ 40,5

P 322 Z ■ 25,5
P 323 Z ■ 30,5